## **Horizontal Sanders & Polishers**



## **Quick Order Number**

This chart has been provided as a means to quickly identify a particular tool. The ordering numbers listed represent the most common versions of our tools. If more specialized versions are required, please build your model number per the following model number flow chart.


	Model Number	Rated Speed	Output Type	
			T5/8 - 5/8-11 Spindle	S1 - 1 or 5/8 Inch Adapter
	500H1M	4000 RPM	500H1MT5/8	500H1MS1
	500H2M	1000 RPM	500H2MT5/8	500H2MS1

## Air Inlet Size: 1/2" NPT (1/2" BSP Available) **Hose Size Recommendations: 1/2" (13 mm) Extra Charge Accessories**

· Safety Lever

## **Standard Equipment**


- Tool Wheel Flange Wheel Nut Wrench
- Operating Instructions and Service Manual
- · Side Handle








35 cfm Max (16.5 L/s)







\* The Spade Handle (G) Adds 1 Lb. (0.45 Kg) To Weight Of Tool


















20 cfm (9.4 L/s) Free Speed 40 cfm (18.9 L/s) Max

\*\* The 520H2 double planetary geared tools adds 2.15 Inch (54.6mm) to overall length. The Spade Handle (G) Adds 1 Lb. (0.45 Kg) To Weight Of Tool

500H1M K S1; 4000 **Example Model Number:** 



Geared Tool

TGOVERNOR CONTROLLED TOOL



